



Notice Page 1

Date: JULY 9, 2025

BRENDA MARCOMBE P O BOX 272 BROUSSARD, LA 70518

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 153 CHESTNUT ST., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number:118E-05-138-008.0H

PPIN Number: 30946

Street Address: 153 CHESTNUT ST., LAUREL MS 39440.

Date: JULY 9, 2025

Address: 153 CHESTNUT ST., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is JULY 19, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely

TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Date: JULY 9, 2025

Address: 153 CHESTNUT ST., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 153 CHESTNUT ST., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.





Notice Page 1

Date: JULY 9, 2025

JACQUELINE MCINNIS 610 ARCO LN LAUREL, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 610 ARCO LN., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number:118D-05-01-010.00

PPIN Number: 11881

Street Address: 610 ARCO LN., LAUREL MS 39440.

Date: JULY 9, 2025

Address: 610 ARCO LN., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the shed located on the property described on page 1. Based on that inspection, the Inspection Department has determined the shed is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the shed such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the shed you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

Thes shed is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the shed, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is JULY 19, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely

TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Exhibit A

Date: JULY 9, 2025

Address: 610 ARCO LN., Laurel, MS 39440

The following deficiencies have been noted for the shed located at 610 ARCO LN., Laurel, MS.

These deficiencies must be corrected in order for the shed to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.





Notice Page 1

Date: JULY 16, 2025

KARLEE HENDERSON 98 VICTORY RD LAUREL, MS 39443

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 1113 N MISSISSIPPI AVE., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number:135N-32-02-007.00

PPIN Number: 9595

Street Address: 1113 N MISSISSIPPI AVE., LAUREL MS 39440.

Date: JULY 16, 2025

Address: 1113 N MISSISSIPPI AVE., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is JULY 26, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely

TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Date: JULY 26, 2025

Address: 1113 N MISSISSIPPI AVE., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 1113 N MISSISSIPPI AVE., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.





Notice Page 1

Date: JUNE 19, 2025

SYMBIOTIC PARTNERS LLC MSC 378 P O BOX 850001 ORLANDO, FL 32885

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 124 W 19TH ST., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number:135E-29-13-012.00

PPIN Number: 10152

Street Address: 124 W 19TH ST., LAUREL MS 39440.

Date: JUNE 19, 2025

Address: 124 W 19TH ST., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs MUST BE APPROVED by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated. the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is JUNE 29, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Date: JUNE 19, 2025

Address: 124 W 19TH ST., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 124 W 19TH ST., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.