

The City of Laurel Mississippi

Post Office Box 647
Laurel, Mississippi 39441

Notice Page 1

Date: APRIL 30, 2025

RONALD B SIMS JR
3526 JACKSON AVE
BATON ROUGE, LA 70802

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 822 CONTI ST., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number:135K-32-01-060.00

PPIN Number:10965

Street Address: 822 CONTI ST., LAUREL MS 39440.

Our records indicate that you are the owner of the above-described property. Also, the Jones County tax records indicate that this property is assessed to you. If this property has recently been sold, please contact the Inspection Department with the updated information. If this property is no longer owned by you, or has been sent in error, please contact the inspection department at (601) 428-6438 or (601) 422-3391.

Notice Page 2

Date: APRIL 30, 2025

Address: 822 CONTI ST., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "**Exhibit A**" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is MAY 09, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely


TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Exhibit A

Date: APRIL 30, 2025

Address: 822 CONTI ST., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 822 CONTI ST., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

**NOTICE: FAILURE TO LIST AN ITEM THAT NEEDS REPAIR OR REPLACEMENT DOES NOT
CONSTITUTE A WAIVER OF THAT ITEM.**



The City of Laurel Mississippi

Post Office Box 647
Laurel, Mississippi 39441

Notice Page 1

Date: MAY 07, 2025

ELIAS THOMAS EST
2110 N 5TH AVE
LAUREL, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 104 S DR DEBORRAH HYDE AVE., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number: 118F-05-02-007.00

PPIN Number: 14646

Street Address: 104 S DR DEBORRAH HYDE AVE., LAUREL MS 39440.

Our records indicate that you are the owner of the above-described property. Also, the Jones County tax records indicate that this property is assessed to you. If this property has recently been sold, please contact the Inspection Department with the updated information. If this property is no longer owned by you, or has been sent in error, please contact the inspection department at (601) 428-6438 or (601) 422-3391.

Notice Page 2

Date: MAY 07, 2025

Address: 104 S DR DEBORRAH HYDE AVE., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "**Exhibit A**" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.


All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is MAY 17, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely, 

TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Exhibit A

Date: MAY 07, 2025

Address: 104 S DR DEBORRAH HYDE AVE., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 104 S DR DEBORRAH HYDE AVE., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

NOTICE: FAILURE TO LIST AN ITEM THAT NEEDS REPAIR OR REPLACEMENT DOES NOT CONSTITUTE A WAIVER OF THAT ITEM.



The City of Laurel

Mississippi

Post Office Box 647
Laurel, Mississippi 39441

Notice Page 1

Date: MAY 07, 2025

ELIAS THOMAS EST
2110 N 5TH AVE
LAUREL, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 110 S DR DEBORRAH HYDE AVE., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number: 118F-05-02-007.00

PPIN Number: 14646

Street Address: 110 S DR DEBORRAH HYDE AVE., LAUREL MS 39440.

Our records indicate that you are the owner of the above-described property. Also, the Jones County tax records indicate that this property is assessed to you. If this property has recently been sold, please contact the Inspection Department with the updated information. If this property is no longer owned by you, or has been sent in error, please contact the inspection department at (601) 428-6438 or (601) 422-3391.

Notice Page 2

Date: MAY 07, 2025

Address: 110 S DR DEBORRAH HYDE AVE., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "**Exhibit A**" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is MAY 17, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely

TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Exhibit A

Date: MAY 07, 2025

Address: 110 S DR DEBORRAH HYDE AVE., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 110 S DR DEBORRAH HYDE AVE., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

**NOTICE: FAILURE TO LIST AN ITEM THAT NEEDS REPAIR OR REPLACEMENT DOES NOT
CONSTITUTE A WAIVER OF THAT ITEM.**



The City of Laurel Mississippi

Post Office Box 647
Laurel, Mississippi 39441

Notice Page 1

Date: APRIL 30, 2025

GWENDOLYN HUTTO LEE
1736 W 125TH ST
LOS ANGELES, CA 90047

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 611 MASONITE DR., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number: 118E-05-22-002.00

PPIN Number: 14283

Street Address: 611 MASONITE DR., LAUREL MS 39440.

Our records indicate that you are the owner of the above-described property. Also, the Jones County tax records indicate that this property is assessed to you. If this property has recently been sold, please contact the Inspection Department with the updated information. If this property is no longer owned by you, or has been sent in error, please contact the inspection department at (601) 428-6438 or (601) 422-3391.

Notice Page 2

Date: APRIL 30, 2025

Address: 611 MASONITE DR., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "**Exhibit A**" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is MAY 09, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely



TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOR

Exhibit A

Date: APRIL 30, 2025

Address: 611 MASONITE DR., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 611 MASONITE DR., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards


Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

**NOTICE: FAILURE TO LIST AN ITEM THAT NEEDS REPAIR OR REPLACEMENT DOES NOT
CONSTITUTE A WAIVER OF THAT ITEM.**



The City of Laurel Mississippi

Post Office Box 647
Laurel, Mississippi 39441

Notice Page 1

Date: April 16, 2025

DEBORAH MCSWAIN
610 VAN BUREN ST
LAUREL, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 610 VAN BUREN ST., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number: 134O-31-12-002.00

PPIN Number: 12795

Street Address: 610 VAN BUREN ST., Laurel, MS. 39440.

Our records indicate that you are the owner of the above-described property. Also, the Jones County tax records indicate that this property is assessed to you. If this property has recently been sold, please contact the Inspection Department with the updated information. If this property is no longer owned by you, or has been sent in error, please contact the inspection department at (601) 428-6438.

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems due to a fire. A list of specific deficiencies is attached to this letter as "**Exhibit A**" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

C: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice. The deadline is April 26, 2025

Notice Page 2

Date: April 16, 2025

Address: 610 VAN BUREN ST., Laurel, MS 39440

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.


If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is April 26, 2025

D: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Please give this notice the immediate attention it requires. If you have any questions do not hesitate to the Inspection Department.

Sincerely,

A handwritten signature in black ink, appearing to read "Shikinia Kennedy-Ward", written over a horizontal line.

Shikinia Kennedy-Ward
Code Enforcement Officer

Exhibit A

Notice Page 3

Date: April 16, 2025

Address: 610 VAN BUREN ST., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 610 VAN BUREN ST., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards


Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

**NOTICE: FAILURE TO LIST AN ITEM THAT NEEDS REPAIR OR REPLACEMENT
DOES NOT CONSTITUTE A WAIVER OF THAT ITEM.**



The City of Laurel Mississippi

Post Office Box 647
Laurel, Mississippi 39441

Notice Page 1

Date: APRIL 16, 2025

KEVIN LYON
34 LYON DR
LAUREL, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 912 N 10TH AVE., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number: 134O-31-12-002.00

PPIN Number: 8100

Street Address: 912 N 10TH AVE., Laurel, MS. 39440.

Our records indicate that you are the owner of the above-described property. Also, the Jones County tax records indicate that this property is assessed to you. If this property has recently been sold, please contact the Inspection Department with the updated information. If this property is no longer owned by you, or has been sent in error, please contact the inspection department at (601) 428-6438.

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems due to a fire. A list of specific deficiencies is attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

C: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice. The deadline is APRIL 26, 2025

Notice Page 2

Date: APRIL 16, 2025

Address: 912 N 10TH AVE., Laurel, MS 39440

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.


If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is APRIL 26, 2025

D: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Please give this notice the immediate attention it requires. If you have any questions do not hesitate to the Inspection Department.

Sincerely,

A handwritten signature in black ink, appearing to read "Shikinia Kennedy-Ward", written over a horizontal line.

Shikinia Kennedy-Ward
Code Enforcement Officer

Exhibit A

Notice Page 3

Date: APRIL 16, 2025

Address: 912 N 10TH AVE., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 912 N 10TH AVE., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

**NOTICE: FAILURE TO LIST AN ITEM THAT NEEDS REPAIR OR REPLACEMENT
DOES NOT CONSTITUTE A WAIVER OF THAT ITEM.**