



Notice Page 1

Date: April 23, 2025

COCKRELL OBERGE 225 N 18TH AVE. LAUREL, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated carport located at 225 N 18^{th} Ave., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number: 119C-01-07-018.00

PPIN Number: 9205

Street Address: 225 N. 18th Ave. LAUREL MS 39440.

Date: April 23, 2025

Address: 225 N. 18th Ave.., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the carport located on the property described on page 1. Based on that inspection, the Inspection Department has determined the carport is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the carport such as: dilapidated roof/structure. A list of specific deficiencies is attached to this letter as "Exhibit A" on page 3.

This carport is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, or demolish the carport and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the carport you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The carport is currently unsafe. As the owner of the property, it is your responsibility to have or keep the carport vacated.

If you elect to demolish the carport, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is May 3, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the carport demolished. The cost of said demolishing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Please give this notice the immediate attention it requires. If you have any questions do not hesitate to the Inspection Department.

Sincerely,

Donelle Thornton, Field Inspector

Exhibit A

Date: April 23, 2025

Address: 225 N. 18th Ave., Laurel, MS 39440

The following deficiencies have been noted for the carport located at 225 N. 18th Ave., Laurel, MS.

These deficiencies must be corrected in order for the carport to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.





Notice Page 1

Date: April 23, 2025

Wooten John F III & Joseph R 1830 Lee St. Laurel, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 1830 Lee St., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number: 119N-12-04-007.00

PPIN Number: 14085

Street Address: 1830 Lee St., LAUREL MS 39440.

Date: April 23, 2025

Address: 1830 Lee St., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is May 3, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Please give this notice the immediate attention it requires. If you have any questions do not hesitate to the Inspection Department.

Sincerely,

Donelle Thornton, Field Inspector

Exhibit A

Date: April 23, 2025

Address:1830 Lee St., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 1830 Lee St., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated wall, ceiling, floor and roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.





Notice Page 1

Date: APRIL 16, 2025

SHOW ME INVESTMENTS LLC STEVEN J SHROFF 5351 HAGEMANN CROSSING DR ST LOUIS, MO 63128

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 209 S DR DEBORRAH HYDE AVE., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number:118E-05-05-013.00

PPIN Number: 14644

Street Address: 209 S DR DEBORRAH HYDE AVE., LAUREL MS 39440.

Date: APRIL 16, 2025

Address: 209 S DR DEBORRAH HYDE AVE., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is APRIL 25, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely

TALANA FAGAN, CODE ENFORCEMENT/ FIELD INSPECTOF

Exhibit A

Date: APRIL 16, 2025

Address: 209 S DR DEBORRAH HYDE AVE., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 209 S DR DEBORRAH HYDE AVE., Laurel, MS. 39440

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.





Notice Page 1

Date: APRIL 16, 2025

JAMES C MCCORMICK ET AL 420 E 3RD ST LAUREL, MS 39440

From: City of Laurel's Inspection Department

A: SUBJECT PROPERTY:

Dilapidated residence located at 221 S MERIDIAN AVE., Laurel, MS. 39440.

This notice is in regards to the legally described property as follows:

Parcel Number:118F-05-05-005.00

PPIN Number: 9921

Street Address: 221 S MERIDIAN AVE., LAUREL MS 39440.

Date: APRIL 16, 2025

Address: 221 S MERIDIAN AVE., Laurel, MS 39440

B: Inspection Department's Decision:

An inspection has been made of the structure located on the property described on page 1. Based on that inspection, the Inspection Department has determined the building is in an unsafe, and/or unfit condition for occupancy. There are deficiencies in the structure such as: dilapidated structure, unsecure structure, plumbing, mechanical and/or electrical systems. A list of specific deficiencies are attached to this letter as "Exhibit A" on page 3.

This property is in such a state of disrepair so as to be a threat to the public health, safety of the adjoining property owners and the community. Therefore, it is requested that action be taken to repair, secure or demolish the building and to clean the lot on which the structure is located.

D: OWNERS OBLIGATION

If you choose to repair the structure you must obtain all necessary permits within ten (10) DAYS of the date of this notice.

All repairs must be made in compliance with the International Building Code, which the City of Laurel has adopted. A building permit is required and must be obtained in the Inspection Department at City Hall. All repairs **MUST BE APPROVED** by Building Inspector in advance.

The building is currently unsafe and/or unfit for occupancy and must be or remain vacated. As the owner of the property, it is your responsibility to have or keep the building vacated. While vacated, the building must remain secure against unauthorized entry. Persons found in the structure are subject to removal and/or municipal citations.

If you elect to demolish the structure, a demolition permit must be obtained within ten (10) days from the date of this notice. The deadline is APRIL 25, 2025.

E: FAILURE TO TAKE ACTION

If you fail to respond or act as directed to this notice, it will result in the City of Laurel taking action to have the structure secured and/or demolished. The cost of said securing will be assessed to the Property Identification Number associated with this property and subject you to legal proceedings.

Sincerely

TALANA FAGAN, CODE ENFORCEMENT/ FIELD WSPECTOR

Exhibit A

Date: APRIL 16, 2025

Address: 221 S MERIDIAN AVE., Laurel, MS 39440

The following deficiencies have been noted for the structure located at 221 S MERIDIAN AVE., Laurel, MS.

These deficiencies must be corrected in order for the structure to meet the minimum standards of the International Residential Building Codes and the City of Laurel's Ordinance.

Deficiencies are as follows:

Deficiency: Dilapidated roof structures.

Compliance: Repair or replace all items to meet code standards.

Deficiency: Dilapidated exterior and interior components

Compliance: Repair or replace all damaged components to meet code standards

Deficiency: Dilapidated plumbing

Compliance: Repair or replace to damaged plumbing to meet code standards

Deficiency: Dilapidated electrical and wiring and components

Compliance: Repair or replace to meet electrical code standards

Deficiency: A vacant structure that is not secured against entry will be deemed unsafe. All openings into a vacant structure must be so secured so as to prevent entry. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.

Compliance: Secure all openings. Openings shall be defined as windows, doors, crawl spaces or any other means of ingress or egress.